Winter—Spring Report 2012



188 East 70

188 East 70th Street Condominium Association Board of Managers Newsletter

ELEVATORS!

RENOVATION ALMOST DONE

The residential and doctors' office elevator renovation has been completed!

The entire mechanical system, the motors and the electronic control systems have been replaced. Only the cab that you ride in is the same. You do see a new button panel, but that is the only evidence that the elevator is brand new.

The service elevator is the last step in the process. It will be out of commission for about twelve weeks, One of the passenger elevators will be used for both passengers and service until this project is complete.

Everything You Don't See Is New.

The residential and doctors' office elevator renovation has been completed!

The entire mechanical system, the motors and the electronic control systems have been replaced. Only the cab that you ride in is the same. You do see a new button panel, but that is the only evidence that the elevator is brand new.

What's new?

- · All cables
- · All tracks and rails
- · All motors
- · Electronic controls
- · Control room air conditioner

The original elevator system was proprietary to the elevator company that installed it. This forced us to rely on that one company for service, ultimately causing delays and locking us in to contracts with them.

The new system is state of the art but not proprietary and will





The master control panel for the computerized control units for the new elevator systems.

allow us greater flexibility in contracting for maintenance.

The service elevator is the last step in the process. It will be out of commission for about

twelve weeks, One of the passenger elevators will be used for both passengers and service until this project is complete.

What Are We Doing to Prevent Potential Damage From Leaks?

Board of Managers

President
J. Jay McAndrews
Vice President
Lenore Robins
Secretary
Holly Heston Rochell
Treasurer
Berk Mesta

Sara A. Ricciardi

Jacob Frenkel

Irwin Merkatz

Members

We have installed water leak sensors (inset) in the cooling tower, the FDNY water tank room and the 30th floor pump room. The sensors are the units described in the 2008 Spring report. Read the story at—www.188e70.com/newsletters.

It was tricky, but our ingenious staff figured out how to get a phone line from the front desk to the 30th floor to the sensor control unit.

We will now know immediately about any water problems in those areas.



Page 2 188 East 70

Backflow Valves and New Water Shutoff



Backflow valves are now inserting new valves into a either or both main water offices were required by New York City code for the water supply for all buildings. We have been able to install these valves with no service interruptions.

This very complex task of make it possible to shut

plumbing contractors.

new shutoff valves that



major pipe system is done supply lines without having designed to be a garage professional outside to access the professional where access would not office area.

The plumbers were able to This has been a problem for The installation of these do this job and also install the building since it opened because the professional

have been a problem.

new valves will be a major enhancement to building water system.

Wireless Internet Service

Wireless Internet is available throughout the second floor. Look for 188 East 70 in the gym and 188 East 70 EXT in the playroom and atrium. The password is available at the concierge.








New Treadmill and 55" Flat Screen in Gym





The gym has two new features that work together—a beautiful, big Matrix treadmill and a 55" flat screen TV to keep up with the market or the news while you do some running in the morning.

Professional Offices Upgraded









The professional office suite has been upgraded with a brass plaque listing for the doctors, new ceiling, lighting and flooring in the lobby and new paint and artwork* for the B1 hallway.